



**Washington State
Department of Transportation**

Field Note Record

Contract No. C8127	Station LW Hillside	Mile/Line: Project Limits	C/S
Staked by WSDOT	Date 	Work Started Date 6/3/2019	Work Completed Date
Calculated by Colton Peyser	Date 8/5/2019	Checked by E. Knudson	Inspector Colton Peyser
		Date 8/14/2019	Date 8/5/19

BI 212

Top Soil Type A

Contractor Installed .99 Acres of top soil type A.

Top soil mixed 50% silt loam and 50% fine compost at the Boot has been place along the LW hillside ditch from LW 1528+90 to LW 1428+00 ; LW 1406+00 to LW 8366+00; LW 8352+00 to LW 8338+00 Approximately.

OK TO PAY .99 ACRE

All Calculations were measured by Mike Muir with a calibrated wheel.

See attached plan sheets for calculation and locations.

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
212.02	Silty Loam Type A	Crystal Springs Stock Pile	Silty Loam Type 1	RAM-0341	8	/ Satisfactory Test Report
212.03	Compost	Cedar Grove Composting Inc.	Compost; Coarse, Medium and Fine	QPL-0318	1135	/ Satisfactory test report from an independent STA program certified laboratory or See Current QPL

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Posted By Init.	Posted By Date	Checked By Init.	Checked By Date	Est. No.
0212	TOPSOIL TYPE A	1	8/5/2019	ACR E	.99	7383	EK	08/14/19			93

Attachments



Bid item 212 back up
2019.pdf
Adobe Acrobat Document
750 KB



C8127 Fine Compost BI
213.pdf
Adobe Acrobat Document
399 KB



Top Soil 212.pdf
Adobe Acrobat Document
859 KB



File Attachment



Acreage Top Soil Item
212.xlsx
Microsoft Excel
Worksheet
11.6 KB